

TILSTANDSRAPPORT

Stamdata

Registreringsnummer	CP56960	Stelnummer	WF0EXTTREKM32028	Reg. Attest	Del I
Mærke	FORD	Model	TRANSIT	Version	2.0TDCi - FWD (170 HK) Kassevogn FWD A6
Karrosseritype		Farve		Reg. dato	31-01-2020
Drivkraft	Diesel	Drivlinje	Front wheel drive	Gearstype	Automatisk
KM. stand	168665	Antal nøgler	2	Servicebog tilstede	Elektronisk
Instruktionsbog tilstede	Ja	Afleveringsdato	30-01-2025		

Udvendige billeder



Fabriksudstyr

Trend	Interior color - Ebony	Without roof-mounted turn signals
Seat package 2	Single Stage Vehicle	With rear fog lights
Frozen White	With storage - headliner	Without programmable interface module
Driver assistance package	Interior accent package B	Without wire harness
12V socket in the cargo area	With partial headliner - molded part	Without wiring for roof beacon
3rd key	Without rear overhead storage compartment	Without additional power distribution unit
Airbag* - passenger	With cargo area tie-down strap	Less intelligent fuse box
High roof (H3)	Without bracket - first aid kit	Frozen White
Battery relay (A540)	Without luggage compartment protection set	Manufacturing plant Otosan (Turkey)
Turning light in headlights	Without load shelf	Without media data interface module
Storage in the roof lining of the driver's cab	Without interior partition	Programmable fuel additional heater
Trailer Stability Program (TSA)	Glasses compartment - roof - driver side	Cold start -29 degrees C
Anti-lock braking system (ABS)	Without access ladder	Visibility Package 3
Front-wheel drive	Chrome-plated	Visibility Package 3
Electrically adjustable and heated exterior mirrors	Body-colored molded part - Gray	Less special value packages
Turn signal integrated in exterior mirrors	Less Rear Window Protector	With High Roof
Vinyl flooring in the cargo/passenger compartment	Without rear step	Standard panel van
On-board computer	Without side auxiliary step	With High Roof
Entry lights	Large mirror head/Short foot	With High Roof
Electronic brakeforce distribution (EBD)	With 2-way Adj. K.Stütze, Front	With High Roof
Electronic Stability Program (ESP)	Without table - front seat	With High Roof
Electronic traction control	Without rear headrests	Roof-mounted radio antenna
Hill start assist	Without center armrest - rear seat	Doub. elect. adj. Mirrors-El. f. fold
Emergency brake assist	Without rear seat back inclination adjustment	With headlight range control front

Crosswind assist	Without 6th row of seats	With fog lights
Electric windows	Without rear seat in 2nd row	With automatic headlight control system
Cruise control	Without rear seat in 4th row	With daytime running lights
Automatic SelectShift transmission - (6-speed)	Without fifth row of seats	Headlights statically swiveling
Rear doors (opening angle 180 degrees)	No 3-seater 2nd row seat against direction of travel	With additional brake light
Heating with recirculation switch	Driver's seat 4-adjustable seat cushion tilt	High-beam LED mid. speed light
Body type: High roof van	Passenger seat 4-way adjustable seat cushion tilt	With windscreen wiper automatic control
Body variant: Medium roof	Without rear seat packages	With mud flaps, Rear
Air conditioning	Without trailer tie-downs	Front bumper partially body-colored
Adjustable steering column	Rear axle alternative A	With tinted windows, Standard
Engine 2.0 Ltr. - 125 kW TDCi KAT	Less Trailer Sway Control (TSC)	With tinted windows, Standard
My Key (2nd programmable vehicle key)	LESS EMERGENCY HAMMER	For heated windscreen only
Front and rear parking sensors	Without device dock	ICE Multim.-System Ausr. 20
Wheelbase 3750 mm	Without tablet holder	With steering wheel radio controls
Tire repair kit	With plastic gear shift knob	Radio Loudspr.-2 Low-/2 High-tone
Particulate filter	With auto. Door locking – Activated	MFD TFT Touch Screen
Low emissions according to emission standard Euro 6d-TEMP	Less Zonal Opposite Door Relocking	ICE Multim.-System Ausr. 20
Leather gear shift knob	Configurable Unlocking - Conf 1	With on-board computer
Windshield wipers with interval control, adjustable	Power Lock Group-Speed Dependent	With rear parking sensors
Sliding door cargo/passenger compartment on the right	Without Ford Key Free System	With front parking sensors
Rear mud flaps	With manual locking	With rear parking sensors
Side protection strips	Without rear window wiper/washer	With speed control system
Start/stop system	Warning light - Washer fluid level	With driver airbag
Daytime running lights	Without underbody corrosion protection	With passenger airbag

Trend	Without body side stripes	With passenger airbag
Integrated rear step	Rear bumper plastic unpainted	With deactivation of passenger airbag
Panelling in cargo/passenger compartment: high	Without bumper underguard rear	Plastic bulkhead with window
Panelling in cargo/passenger compartment: vinyl	Without bumper underride protection front	Grill - Rear wall/Partition
Load securing rings (10)	Without head protection airbag	Floor c. - plastic insert - part.
Roll stability control (RSC)	Without head protection airbag right	Cargo space trim - molded part
Lightly tinted heat-insulating glass	With front seat belt retractor	With lockable glove comp. cover
Central locking with remote control	Without rear seat belts	Cargo space trim - molded part
Electric auxiliary heater	Safety belt - black	With complete rear trim hardboard
Second key with remote control	Without Isofix attachment	Manual air conditioning control
Front axle load increase to 1.85 t	Belt tensioner - driver's safety belt	With pollen filter
Passenger side airbag	Without driver/passenger side airbags.	With circulation heating
Driver side airbag	Without spare wheel release	With heated driver's seat
Audio system 20: Radio with 8" multifunction display	Without tire pressure sensors	With heated passenger seat
Cold start package	With single rear tires	Standard front seats
Cargo area light LED	Wheel nuts without wheel lock	With manual driver lumbar support
Plastic cargo partition with window	Without engine speed control	With manual passenger lumbar support
Visibility package 3	With dust shield - brake	With driver seat armrests
Seat package 14: Driver's seat (4-way adjustable) - Passenger single seat (4-way adjustable) including seat heating, fabric	3.39	With passenger seat armrests
Steel wheels 6.5x16	Without front differential	Without 3rd row seat
Stand-heating package 1	With black and white exhaust pipe	El. front windows with tip function.
12V socket in the cargo/passenger compartment	With mechanical parking brake	With central locking
Capitol/City Ebony	Without collision avoidance system	With central locking
Without underbody protection	Without rear seat climate control	Remote door entry - 2 Fob

Without roof conversion	Without ventilation system	Two-stage entry system - Door
Mini-Media-Hub (2XUSB) Adp BSL + BT	Refrigerant - R134A air conditioning	Two-stage entry system - Door
Without mud flaps, front	Without additional fuel filler necks	Remote door entry - 2 Fob
With unimpeded side door opening	With simple fuel tank	My Key
Without foldable treadplate - steel loading door	Fuel inlet without cap without lock	Fleet key
Without 2nd freestanding structure	With diesel switching possibility	With rear doors
Without grid bulkhead - 2nd unit	Fuel filler neck with lock	With rear doors
Less Tailboard Support Straps	Without rear interior heating	With side loading doors curb side
Less Auxiliary I/P Console	With speedometer (km/h)	With cargo area lighting
With standard permissible total weight	Without tachograph	Without interior mirror
Without security locking	Without navigation system	With socket – rear
Without special equipment kit	Vehicle emergency system	Rearview camera, fixed
Without special paintwork	Without warning/reverse gear	Front axle load - maximum
With SVO application/sign	Less Mass Movement Sensor	6.5 X 16" Steel Wheel
Less Diagnostic Maintenance Monitor	Without blind spot information system	With full wheel cover
Without engine equipment group	Without lane keeping assist	Without spare wheel
Uni paintwork	Without theft warning system	Tire repair kit
Without cooling equipment	Without vehicle tilt detection	With leather-wrapped steering wheel
Without SVO except packages	Without lateral parking assistance	With manual adjustable steering column
Without stickers - VP application	Without automatic parking assistance	Brakes – ESP/HLA/FBS
Without certification stickers	Less deep discharge batteries	Lane Change Warning System
Without SVO marketing packages	Without inverter	Lane Change Warning System
LESS MARKETING COMFORT PACK	Without A/V connection	Brakes – ESP/HLA/FBS
Without fire extinguisher brackets	ICE-Low with improved connectivity	LHD FWD
Without fire extinguisher	ICP - Mini Electronic Cover	High performance battery
Without tool kit	Microphone	Extended shut-off relay
Without kit	Without voice control modules	With spec. high-perf. alternator.

No side windows in 2nd row, right	Without socket	6-speed automatic transmission 6F55
No side windows in 2nd row, left	Without front video camera	Emission standard 6.2
No side windows in 3rd row, right	Without safe box	Emission standard 6.2
No side windows in 3rd row, left	Without rear dual tire package	Emission standard 6.2
No side windows in 4th row, right	With halogen headlights	Starter - stop/start system
No side windows in 4th row, left	Less Headlamps - Wiper Activated	CVH 1.6 CFI
Without rear window	Less Roof Marker/Clearance Light	CVH 1.6 CFI
Without heated rear window	Without light packages	CVH 1.6 CFI
Without console ashtray	With roof-mounted interior/map lights	Without engine speed control
With standard headliner	Without overhead reading lights	Marketing level 4
Interior color Dark Palazzo Grey	Without side marker lights	

Dæk og mønster

Position	Mærke	Størrelse	Slidbane	Dæktype
Venstre, For	Hankook	235/65-16	04 mm	Vinter
Venstre, Bag	Continental	235/65-16	04 mm	Vinter
Højre, Bag	Continental	235/65-16	04 mm	Vinter
Højre, For	Continental	235/65-16	04 mm	Vinter

Ekstra hjul

Ekstrahjul tilstede Ja

Position	Mærke	Dæktype
Ekstrahjul	Bridgestone	Sommer

Reservedæk og rep. kit


Rep. kit tilstede

Findes ikke

Reservehjul tilstede

Nej

Præsentationsbilleder



Mangler / Tilstand

Ref	Sted	Del	Type	Handling
#1	GDPR Gebyr	GDPR Gebyr	Opkrævning	K5
#2	Mellem folie	Mellem folie	Ikke afmonteret	K5

Skader

Ref	Sted	Del	Type	Handling
#1	Interiør	Instrument bord	Hul	K3
#2	Forrude	Rude	Stenslag	K5
#3	V. fordør	Dør	Bule(r)	K3
#4	V. bagskærm	Sidevæg	Bulet/Ridset	K4
#5	Bagklap	Venstre bagdør	Ridser	K3
#6	Bagklap	Højre bagdør	Bulet/Ridset	K3
#7	H. bagskærm	Skærm	Bule(r)	K4
#8	H. bagdør	Skydedør	Ridser	K4
#9	H. panel	Indstigning Højre Bag	Bulet/Ridset	K4
#10	Tag	Tagplade	Rust plet	K4




1

Sted Interiør
Del Instrument bord
Type Hul



1A

Sted Interiør
Del Instrument bord
Type Hul



2

Sted Forrhude
Del Rude
Type Stenslag



2A

Sted Forrhude
Del Rude
Type Stenslag



2B

Sted Forrhude
Del Rude
Type Stenslag



2C

Sted Forrhude
Del Rude
Type Stenslag




2D

Sted Forrhude
Del Rude
Type Stenslag



3

Sted V. fordør
Del Dør
Type Bule(r)




3A

Sted V. fordør
Del Dør
Type Bule(r)



4
 Sted V. bagskærm
 Del Sidevæg
 Type Bulet/Ridset




4A
 Sted V. bagskærm
 Del Sidevæg
 Type Bulet/Ridset



4B
 Sted V. bagskærm
 Del Sidevæg
 Type Bulet/Ridset



5
 Sted Bagklap
 Del Venstre bagdør
 Type Ridser



5A
 Sted Bagklap
 Del Venstre bagdør
 Type Ridser



6
 Sted Bagklap
 Del Højre bagdør
 Type Bulet/Ridset



6A
 Sted Bagklap
 Del Højre bagdør
 Type Bulet/Ridset



7
 Sted H. bagskærm
 Del Skærm
 Type Bule(r)



7A
 Sted H. bagskærm
 Del Skærm
 Type Bule(r)




7B

Sted	H. bagskærm
Del	Skærm
Type	Bule(r)



7C

Sted	H. bagskærm
Del	Skærm
Type	Bule(r)



8

Sted	H. bagdør
Del	Skydedør
Type	Ridser



8A

Sted	H. bagdør
Del	Skydedør
Type	Ridser



8B

Sted	H. bagdør
Del	Skydedør
Type	Ridser



9

Sted	H. panel
Del	Indstigning Højre Bag
Type	Bulet/Ridset



9A

Sted	H. panel
Del	Indstigning Højre Bag
Type	Bulet/Ridset



9B

Sted	H. panel
Del	Indstigning Højre Bag
Type	Bulet/Ridset




10

Sted	Tag
Del	Tagplade
Type	Rust plet



Sted	Tag
Del	Tagplade
Type	Rust plet



Sted	Tag
Del	Tagplade
Type	Rust plet

Evt. Mekaniske fejl

Bemærkninger vedr. mekaniske fejl
