

Date
Inspection
no.
Performed

Department

46288

Odense

SAL FDM Test & Bilsyn

06-02-2025 15:40

TILSTANDSRAPPORT

Stamdata

Registreringsnummer	CE73839	Stelnummer	WF0YXXTTGYJA58296	Reg. Attest	Del I
Mærke	FORD	Model	Transit Custom Van	Version	2.0TDCi - FWD (170 HK) Kassevogn FWD M6
Karrosseritype		Farve		Reg. dato	29-01-2019
Drivkraft	Diesel	Drivlinje	Front wheel drive	Geartype	Manuel
KM. stand	233241	Antal nøgler	2	Servicebog tilstede	Elektronisk
Instruktionsbog tilstede	Ja				

Udvendige billeder













Date Inspection no.

Performed

Department

46288

SAL

FDM Test & Bilsyn Odense

06-02-2025 15:40

Fabriksudstyr

Trend	Without rear roof compartment	Manufacturing plant Otosan (Turkey)
Roof bars - Integrated	Without cargo net set	Without lane change warning system
Visibility package	Without first aid box holder	Without blind spot information system
Left sliding door	Without luggage compartment protection set	Programmable fuel additive heater
150 W / 230V socket	Without load shelf	Cold start -29 degrees
Airbag* - passenger	Inner handles - 2	With enhanced visibility package
All-weather tires	Without noise protection packages	Seat package 15
Trailer hitch with trailer sway control	Without roof storage - driver	Less special value- added packages
Auto-Start-Stop	Without access ladder	With low roof
Reverse camera (image displayed on 4" or 8" display)	Without running boards	Standard panel van
Frozen White	With exterior color package 2	Standard panel van
Radio with SYNC 3 + Navigation + DAB	Grill - 3 strut cmpl. colored	With low roof
Turning lights in headlights	Br. caroses. molded part - Gray	With trailer hitch
Driver's side airbag	Less Rear Window Protector	With Trailer Sway Control (TSC)
Anti-lock braking system (ABS)	Without spoiler	With trailer hitch
Drive type: Front- wheel drive	Without auto. mirror tilt sys.	Double el. adjustable ext. mirrEl. folding
Electrically adjustable and heated exterior mirrors	Without passenger seat armrests	With body-colored exterior mirror
Turn signal integrated in exterior mirrors	With 2-way adjust. K.sup., Front	Roof rack integrated/foldable
Flooring: Vinyl in load/passenger compartment	Table - Front seat	Halogen projection headlights
On-board computer	Without rear headrests	With headlight range control front
Electronic brake-force distribution (EBD)	Without center armrest - rear seat	With automatic headlight control
Electronic Stability Program (ESP)	Without rear seat backrest adjustment	Daytime running lights level 2
Electronic traction control	Without lumbar support for passenger seat	With automatic headlights
Assist system: Hill start assist	Seat belt warning - driver's seat	With additional brake light





Date 06-02-2025 15:40
Inspection no. 46288
Performed by SAL

Department

FDM Test & Bilsyn

Odense

Assist system: Emergency Brake Assist	Without rear seat in 2nd row	With windshield wiper automatic front.
Assist Assist Crosswind Assist	Without rear seat in 4th row	With mud flaps, front
Electric windows	Driver's seat. 4-f. adj. seat cushion tilt	With mud flaps, rear
Generator 220 A	Without rear seat packages	With color b-beams, f car c-color
Cruise control	Without device dock	Fog. ht. pt. bd full color
6-speed transmission	O. fuel-saving equip.	With tinted windows, standard
Lockable glove compartment	Black exterior door handle	With tinted windows, standard
Rear swing doors without glazing (opening angle 180 degrees)	Rear door/boot grip out blac	For heated windshield only
Interior filter: Pollen filter	With plastic gear shift knob	Sync III
Body type/high-roof van	Without fleet key	Radio Lautspr2 Tief- /2 Hochtöner
Body variation: Medium roof	With auto. door locking - activated	MFD TFT Touch Screen
Air conditioning	Less Zonal Opposite Door Relocking	Sync III
Tilt/telescopic steering column	Configurable Unlocking - Conf 1	With onboard computer
Truck registration	Power Lock Group- Speed Dependent	With navigation system
Model update	Warning light - Washer fluid lev.	With navigation system
Engine 2.0 L - 125 kW TDCi KAT	Without two-tone body paint	Ice Feature Pack 24
Fog lights	Without underbody corrosion protection	With rear parking aid
Parking pilot system	Without body stripes - side	With front parking aid
Front and rear parking pilot system	Without hood accent stripes	With rear parking aid
Wheelbase 3300 mm	Without head protection airbag	With navigation system
Spare wheel in driving condition	Without head protection airbag right	With speed control system
Particulate filter	With front seat belt retractor	With driver's airbag
Low emissions according to Euro 6 emission standard	Without rear seat belts	With passenger airbag
Windshield wipers with interval setting, adjustable	Safety belt - black	With passenger airbag
Headlights H4	Without Isofix attachment	With deactivation passenger airbag
Sliding door load/passenger compartment right	Driver/passenger seat belt tensioner	Grill - Rear wall/partition





Date
Inspection
no.
Performed
by

Department

46288

SAL

FDM Test & Bilsyn Odense

06-02-2025 15:40

Mud flaps front and	Without driver/passenger side	Partition with loading
rear	airbags	hatch+window
Side protection strips	Spare wheel release	Floor covering - plastic ins partially
Steel rims 6.5x16	Without tire pressure sensors	Load compartment trim-molded part
Start/Stop system	215/65R15 H BSW Tire	With lockable glove compartment lid
Partially painted bumpers	Wheel nuts without rim lock	Load compartment trim-molded part
Style color package	Without engine speed control	Door paneling - side/rear - Level 1
LED daytime running	With standard	Door paneling - side/rear - Level 1
lights	suspension With dust shield -	Programmable fuel
Trend	brake	additive heater
Trim in load/FG space: half-height	Axle ratio 4,188/3,045	Manual control - air conditioning
Lashing eyes (8)	With mechanical handbrake	With pollen filter
Lightly tinted heat- insulating glass	Without collision avoidance system	With auxiliary heating
Central locking with remote control	Without premium brakes	Programmable fuel additive heater
Passenger side airbag	Without rear seat adjustment	Programmable fuel additive heater
Trailer hitch: Fixed ball head	Without climate control - rear seat	Programmable fuel additive heater
Front armrests	Without ventilation system	With heated driver's seat
Audio navigation system Ford SD (with Ford SYNC 3)	Refrigerant - air conditioning R134A	With heated passenger seat
Roof rack in load compartment, foldable	Without additional fuel filler	With Man. 2-way pass. seat adj.
LED load compartment light	With simple fuel tank	With driver single seat/passen. double seat n/R
High load compartment partition behind driver and passenger, with window and load-through possibility below	Fuel filler w/o flap without cap	With man. lumbar support-driver
Rear view camera with color display	With diesel switching option	With driver's seat armrests
Sliding door load/passenger compartment left	Fuel filler cap with lock	Without rear seat in 3rd row
Visibility package 2	Electronic speed limiter	With central locking
Seat package 9 / 15 Driver's seat (4-way adjustable) - Passenger double seat including seat heating, fabric	Without distance regulator	With central locking





06-02-2025 15:40 Date Inspection 46288 no. Performed

by

Department

FDM Test & Bilsyn

SAL

Odense

Standby heater	Without rear interior heater	Remote door entry -2 Fob
Socket 230V / 150 Watt	With simple instrument panel	Two-step entry system - door
Capitol/City Ebony	With speedometer (km/h)	Two-step entry system - door
Without underbody protection	Without tachograph	Remote door entry -2 Fob
Without cargo securing device	Electric dual-tone horn	With 180° cargo door stops
Mini-Media-Hub (2XUSB) Adp BSL+BT	Vehicle emergency system	With rear doors
With unrestricted side door opening	Without reverse warning	Without rear window
Without foldable step side loading door	Without driver impairment monitoring	Without rear windshield wiper/washer
Without rear hatch	Without lane keeping assist	With rear doors
With standard permissible total weight	Without speed limit sign recognition	With double side load doors
Without special equipment set	Without theft alarm system	With double side load doors
Complete vehicle	Without vehicle inclination detection	With load compartment lighting
Without equipment - marketing preparation	Without lateral parking aid	Without interior mirror
Without special paint	Without automatic parking aid	Unlit sun visor - driver's side
Without SVO application/sticker	Less deep discharge batteries	Illum. sun visor passenger mirror
Less Diagnostic Maintenance Monitor	With normal power three-phase generator	With additional socket
Without equipment RSO	Without A/V connection	With additional socket
Uni-paint exterior	MM system Dual/5. Kan./TMC/DAB/PD	8 tie-down loops - cargo area
Without SVO except packages	ICP - Mini Electronic Panel	8 tie-down loops - cargo area
Without stickers - VP application	Without mobile phone interface	Roof rack integrated/foldable
Without certification stickers	Microphone	Rear-view camera, fixed
Without fire extinguisher mounts	Road Bed Steering wheel - with PTT	Rear-view camera, fixed
With tool kit	Voltage output	With Anti-Lock Braking System & ESP+
Without set	Without socket - rear	6 1/2J x 15 steel wheel
Without tire repair kit	Without safe box	With full wheel cap
Front pass. quick- release belt. after FA	With quad headlights	With steel spare wheel
Without side windows in 2nd row, right	Fog lights - curve light	With leather-covered steering wheel
Without side windows in 2nd row, left	Warning reflectors corner rear door	With man. adj steering column





Date
Inspection
no.
Performed
by

Department

46288

SAL

FDM Test & Bilsyn Odense

06-02-2025 15:40

Without side windows in 3rd row, right	Without light packages	With Anti-Lock Braking System & ESP+
Without side windows in 3rd row, left	Without interior lights	LHD FWD
Without heated rear window	With footwell lights	High performance battery
Without console ashtray	With roof-mnt. interior/map lights	High performance battery
With small roof console	Without overhead reading lights rear	High performance battery
Dark Palazzo Grey interior color	Without roof-mounted turn signals	6-speed manual - VMT6
Ebony interior color	Without programmable interface module	With diesel particulate filter
Without storage - headliner	Without battery cut-off relay	Emission standard Stage VI, LNFZ 3
Interior accent package B	Without wiring harness	Starter - Stop/Start system
Without sun visors	Without wiring for roof beacon	2.0L CR TC Diesel Panther C
With partial headliner - molded part	Without additional socket field	Without engine speed control
Without rear coat hooks	Without intell. fuse box	Marketing Level 4
Without grab handle - B pillar	Frost White	With trailer hitch

Dæk og mønster

Position	Mærke	Størrelse	Slidbane	Dæktype
Venstre, For	Continental	215/65-16	04 mm	Helårs
Venstre, Bag	Continental	215/65-16	09 mm	Helårs
Højre, Bag	Continental	215/65-16	09 mm	Helårs
Højre, For	Continental	215/65-16	04 mm	Helårs

Ekstra hjul

Ekstrahjul tilstede Nej

Position Mærke Dæktype





06-02-2025 15:40 Date Inspection 46288 no. Performed SAL FDM Test & Bilsyn Department

Odense

Ekstrahjul

Reservedæk og rep. kit

Rep. kit tilstede Mangler helt Reservehjul tilstede Nej

Position	Mærke	Størrelse	Slidbane
Reservehjul		/-	





Date Inspection no. Performed

Department

by

06-02-2025 15:40 46288

10200

SAL

FDM Test & Bilsyn Odense

Præsentationsbilleder



















06-02-2025 15:40 Date Inspection no. Performed by

Department

46288

SAL

FDM Test & Bilsyn Odense

Mangler / Tilstand

Ref	Sted	Del	Туре	Handling
#1	Stor folie	Stor folie	Ikke afmonteret	K5
#2	Rens af sæder	Sæde VF	Mangler rengøring	K5





Skader

Ref	Sted	Del	Туре	Handling
-----	------	-----	------	----------

Evt. Mekaniske fejl

Bemærkninger vedr. mekaniske fejl