

TILSTANDSRAPPORT

Stamdata

Registreringsnummer	CV20340	Stelnummer	WF0FXXWPMFMJ54927		
Mærke	FORD	Model	KUGA	Version	1.5 EcoBlue (120 HK) Varebil M6 M6
Karosseritype		Farve		Reg. dato	08-03-2021
Drivkraft	Diesel	Drivlinje	Front wheel drive	Geartype	Manuel
KM. stand	265548	Antal nøgler	2	Kontraktnummer	7011002

Udvendige billeder

Fabriksudstyr

Frost White	With 2-way adj pwr driver seat. Front	With Rear Spoiler
Trailer Preparation Package	With Manual Driver Seat Back Angle Lever	With Rear Spoiler
Van 21	With Manual Passenger Seat Back Angle Lever	Rear bumper htn. Body-colored plastic
Ambient Lighting Front (LED)	Seat Mounting Bolster Cover	Grill bars bottom dkl. Own color
Anti-lock Braking System (ABS)	Without Center Swing Table	With tinted windows, standard
Traction Control System (ASR)	Without Rear Seat Armrest	Only For Heated Windshield
Front-Wheel Drive	Sec Row Fore-Aft Adj Seat Track	With Multimedia System Package 14
Audio Navigation System Ford with AppLink	Without Heated Rear Seats	With Radio Controls - Steering Wheel
Electrically Folding Exterior Mirrors	Without Tow Hitch	With 6 Radio Speakers
Electrically Adjustable and Heated Exterior Mirrors	With Tow Hooks, Front	AECS not SMS rollover detection 2G
On-Board Computer	With Tow Hooks, Rear	Mobile Phone Interface - 4
Glasses Compartment integrated in headliner / roof console	Less Trailer Module	Sync III
Fabric Headliner	Ignition Key Equ. Comb. 1	With combiinstr. in high quality Ausst.
Silver Roof Rails	Door Lock Cover Steel	With on-board computer
Roof Spoiler in body color	With Child Safety Lock	With on-board computer
Dual exhaust pipe system	Manual Gear Shift	MFD TFT Touch Screen
Eco Display for fuel-efficient driving (EcoCoach)	With auto. Door Locking - Activated	With rear parking aid
Electronic Stability Control (ESP)	With convenience open/close - Doors	With front parking aid
Driver Assistance System: Emergency Brake Assist	Frequency 433 MHz	With rear parking aid
Driver Assistance System: Post-Collision System	Without heatable washer nozzle	With Navigation System
Driver Assistance System: Pre-Collision System	Trim - Front Bumper Mic	Tire pressure sensors - 433 Mhz
Driver Assistance System: Lane Keeping Assist	Bumper Moulding - Rear Mic	F / B Belt 1./2. Reihe F-Knee Airbag

Electric Windows front + rear with Comfort closing	Without Sensor - Front Bumper	Speed control and ASLD
FordPass Connect including eCall	Front bumper part. Body color	Speed control and ASLD
Carpet Floor Mats	Large License Plate Holder - Rectangle	With driver airbag
Luggage Compartment Cover / Blind	Left Head Protect Airbag	With passenger airbag
Cruise Control (Cruise Control)	Right Head Protect Airbag	With driver airbag
6-speed transmission - Type: B6	Without Rear Side Airbags	With passenger airbag
LED Tail Lights	Without Rear Belt Tensioners	With side airbag - driver side
Inductive charging tray for mobile devices	Without Warnings - Safety G.	With side airbag - passenger side
Interior Mirror with Anti-glare	Without Safety Belt Type	With deactivation passenger airbag
Intelligent Protection System (IPS)	With Front Belt retractor	Center console with armrest (floor)
Isofix child seat mounts	Retractable 3-Pt Safety Belt rear	Center console with armrest (floor)
Body: 5-door	With man. adj. safety. Gurtbef., V.	With Cargo Area Carpet
KeyFree System	Lashing Loops Style 1	Deluxe Headliner
2-Zone Automatic Climate Control	225/65 R17 102V Summer Tires BSW	With Velour Floor Mats front
Front Headrests 4-way adjustable	Without Spare Tire	With Velour Floor Mats rear
Leather steering wheel (3-spoke)	Without Wheel Covers	With Velour Floor Mats front
Steering column (steering wheel) height / length adjustable	Wheel Nuts without Wheel Locks	With Velour Floor Mats rear
Alloy Wheels	With Standard Tires - Every Manuf.	With Velour Floor Mats front
Center Console with Armrest	Wheel Speed Sensor W/Direction Regn	With Velour Floor Mats rear
Engine 1.5 Ltr. - 88 kW EcoBlue TDCi CAT	Without Divider Panels	2-zone air conditioning with auto. Temp. Reg
My Key (2nd vehicle key programmable)	With Kysor Radiator Shutter	Refrigerant - Air conditioning HF01234YF
Fog Lights	Parts for Light alloy wheels only	Pollen / Charcoal Filter
Electric Parking Brake with Auto-Hold Function	With standard cooling fan	With circulation heating
Front and Rear Parking Sensors	No frame-mo. fuel filter	With guideway rear / B-pillar
Wheelbase 2710 mm	Cold start -29 Degrees C	With heated driver's seat
Tire Repair Kit	Without Immersion Heater	With heated passenger seat

Tire Pressure Monitoring System	Without Remote Start	With single seat, high back front
Particulate Filter	No Possible Select From This Family	With single seat, high back front
Rearview Camera	4.056 Final Drive Ratio	With man. 4-way adj. Driver's.
Split-folding rear seat back	With unpainted Calipers	With 8-way passenger seat manually
Foldable rear seat back	Export Fuel Fill	With man. 4-way adj. Driver's.
Low Emission according to Euro 6d emission standard	Without Shift G. with auto. shift	With man. Lumbar support-driver
Leather Gear Shift Knob	Climate fan - Variable Control	M. man. Lumbar support-passenger
Windshield Wipers with Rain Sensor	Less Fuel Tank Lock	With split fold. Rear seat back (60/40)
Headlights with Delayed Shutdown	With Diesel Switching Capability	With foldable seat in the 2nd row
Headlights with Projection Lens Design	Standard Pedal design	Without rear seat in 3rd row
Headlight Assistant with Day/Night Sensor	Electronic Steering Column Lock	With 2-way adj. K.Stütze, Hi.
SCR System (AdBlue Technology)	Without elec. Speed Limiter	With 2-way adj. K.Stütze, Hi.
Electric Power Steering	Without Dist. sensor - Speed control	With center headrest rear
Driver's seat adjustable (8-way)	Without Auxiliary Heater	With center headrest rear
Passenger seat adjustable (8-way)	With Rule Inf. - Comb. Instr.	El. Front windows with tip funct.
Front seat heating	With Speedometer (km/h)	El. Windows rear Heave / Lower
Left sun visor with mirror (illuminated)	Electric horn, One sound	El. Windows rear Heave / Lower
Right sun visor with mirror (illuminated)	Without acoustic warning system	El. Windows rear Heave / Lower
Sports Seats	With Compass Display	El. Front windows with tip funct.
Start / Stop System	Without Media / Entertainment Package	With central locking
Central Locking with Remote Control	No Warning / Reverse gear	With central locking
Trailer Hitch Preparation	Without Monitoring Driv. Impairm.	Only For Remote Unlock - Rear tailgate
Special Paintwork Frost White	Without Speed Limit Sign Detection	With central locking
Ray/Eton / Ebony	Without Theft Alarm System	Keyless Entrance / Start - Passive
Without Underbody Protection	With Theft Alarm System (PATS)	Keyless System
Without Roof Conversion	Without automatic parking assistance	Keyless Entrance / Start - Passive

Without Mudflaps, Rear	Standard power battery	My Key
Media Connection 2 x USB + AV	Gen. - ECO Innovation	Body-colored exterior door handle
106.7" Car Wheelbase	Voltage Regulator-12V Socket	Body-colored exterior door handle
Without Mudflaps, Front	Without inverter	Body-colored exterior door handle
Without Luggage Compartment Mat	AM / FM Antenna	Handle - Tailgate in body color
With manual tailgate	MM System Dual / 5. Can./ TMC / DAB / Pd	With Bright Door Frame Trim
Less Park Lock Ctrl (BTSI Man OvrD)	ICP - Mini Electronics Panel	Belt warning. Driver / Pass. / 2. R. / Eu T&S
No Special Purpose Vehicle	Without ICE Noise Reduction	F / B Belt 1./2. Reihe F-Knie Airbag
Built at the Valencia factory	Without Outlet	Interior Ambient LED
With package for normal performance driver	With 2 additional sockets rear	With Footwell Lights
Ford company emblem	Without Display - Headliner	With electrochromic rearview mirror
Without Equip.-Marketing preparation	Headlamps - Unique	With electrochromic rearview mirror
Without Sales Emblem	With Glove Box Lighting	Sun visor l. illuminated mirror
Without Special Paintwork	With Cargo Area Lighting	Sun visor r illuminated mirror
Without SVO Application/Sticker	With single rear fog light	Voltage output
Without electronic equipment	Without general country groupings	With Leather Shift Knob
Marketing Level 1	Without heated steering wheel	With Isofix attachment
Less Lo-Profile Vehicle Height	Without Special Equipment Set	Mini Roof Cons. with sunglasses holder
Without SIP	Without Windshield Heating Shield	Rearview Camera, fixed
Without Storage Equipment	Without Blind Spot Information System	Wireless Charging
Equipment Content Group 7	With Standard Suspension	Brakes TS / HLA / ESP / TC / ABS
Exterior Paintwork Solid color	Multi-purpose SUV	Brakes TS / HLA / ESP / TC / ABS
Kuga Emblem	Frost White	Front And Rear Disc Brakes
For moderate climates	With Bright Door Frame Trim	Front And Rear Disc Brakes
Without SVO except packages	Stainless Steel Door Covers - Front Door	With rear disc brakes
Without Stickers - VP Application	Without Tow Hitch	With electric parking brake
Without Tailgate Emblem	With Pre-equipment - Towing	Collision Avoidance System
Without Special Language Stickers	With Diversity Antenna	Brakes TS / HLA / ESP / TC / ABS

Without Water Crossing Equipment	Electric adjustable / heated / bli / auto flding / cpr	Collision Avoidance System
Less Tailgate Badges-2nd Level	Electric adjustable / heated / bli / auto flding / cpr	Collision Avoidance System
LESS MARKETING COMFORT PACK	Body-colored exterior mirror	Rear Suspension - Level 2
Less Marketing Driver Assist Pack	Roof rails - silver painted rails	Lane Keeping Assist
Without Jack	Roof rails - silver painted rails	Lane Change Warning System
Without Warning Display	Roof rails - silver painted rails	Lane Keeping Assist
With Rear Luggage Shelf	With Headlights - Level 2	17" Aluminum Wheels - Model 1
Grille-Upper Chrome frame	With Headlights - Level 2	Tire Repair Kit SVC
With Standard Glass Front Side Windows	With headlight range control front	No Spare Tire
Without wind. panel / wiper parking	With fog lights	Leather Steering Wheel (3 spoke)
Without center console ashtray	With fog lights	Leather Steering Wheel (3 spoke)
Interior color Ebony	With fog lights	With man. Adj. - Steering column
Interior color - Ebony	With Daytime Running Lights	With man. Adj. - Steering column
Without Floor Mats 3rd Row	With auto. Ctrl. - Headlights	With electric power steering
Without Kit - Floor Mats	With automatic headlights	Brakes TS / HLA / ESP / TC / ABS
With Aluminum Door Interior Handles	Wrong-way warning function	Brakes TS / HLA / ESP / TC / ABS
4 tie-down loops - cargo area	Taillights - Level 1	LHD FWD
Without cargo net - cargo area	With additional brake light	Brakes TS / HLA / ESP / TC / ABS
Without interior partition	With Daytime Running Lights	6 Speed Manual Trans - B6 Plus
Door Sill Molding - body color	With headlight washer system	Exhaust emissions Euro 6.2
With black belt trim	Windshield wipers front with rain sensor	Starter - Stop / Start system
Lower Molding - interior color	M. Intermittent wash. / wiper, rear	Horizontal twin exhaust chrome plated
Without door edge guards	With automatic headlights	1.5L Duratorq-TDCi - Neo
Without Additional Crossbar Roof Rack	With Bright Door Frame Trim	(-) SVP
With Driver Seat Back Pocket	With Rear Spoiler	
Passenger seat back pocket	With Rear Spoiler	

Dæk og mønster

Position	Mærke	Størrelse	Slidbane	Dæktype
Venstre, For	Continental	225/65-17	07 mm	Vinter
Venstre, Bag	Continental	225/65-17	08 mm	Vinter
Højre, Bag	Continental	225/65-17	07 mm	Vinter
Højre, For	Continental	225/65-17	07 mm	Vinter

Ekstra hjul

Ekstrahjul tilstede Nej



Position	Mærke	Dæktype
Ekstrahjul		

Reservedæk og rep. kit

Rep. kit tilstede Ja Reservehjul tilstede Nej

Position	Mærke	Størrelse	Slidbane
Reservehjul		/-	


Præsentationsbilleder



Mangler / Tilstand


Ref	Sted	Del	Type	Handling
#1	Lille folie	Lille folie	Ikke afmonteret	K4
#2	Rens af sæder	Sæde VF	Mangler rengøring	
#3	Vask og Støvsugning	Bil indvendigt/udvendigt	Mangler rengøring	K4

1




Sted Lille folie
 Del Lille folie
 Type Ikke afmonteret

2



Sted Rens af sæder
 Del Sæde VF
 Type Mangler rengøring

3




Sted Vask og Støvsugning
 Del Bil indvendigt/udvendigt
 Type Mangler rengøring

3A



Sted Vask og Støvsugning
 Del Bil indvendigt/udvendigt
 Type Mangler rengøring

3B




Sted Vask og Støvsugning
 Del Bil indvendigt/udvendigt
 Type Mangler rengøring

Skader


Ref	Sted	Del	Type	Handling
#1	Motorhjelm	Hjelm	Stenslag	K2
#2	Front	Forkofanger	Rids	K4
#3	Bagkofanger	Kofanger	Rids	K1
#4	V. panel	Indstigning Højre For	Ridser	K2
#5	V. fordør	Side spejl	Rids	K4

1




Sted Motorhjelm
 Del Hjelm
 Type Stenslag

2




Sted Front
 Del Forkofanger
 Type Rids

2A




Sted Front
 Del Forkofanger
 Type Rids

3




Sted Bagkofanger
 Del Kofanger
 Type Rids

3A



Sted Bagkofanger
 Del Kofanger
 Type Rids

4



Sted V. panel
 Del Indstigning Højre For
 Type Ridser

5



Sted	V. fordør
Del	Side spejl
Type	Rids

Evt. Mekaniske fejl

Bemærkninger vedr. mekaniske fejl
