

TILSTANDSRAPPORT

Stamdata

Registreringsnummer	CH75640	Stelnummer	WF0YXXTTGYKK54281		
Mærke	FORD	Model	Transit Custom Van	Version	2.0TDCi - FWD (130 HK) Kassevogn FWD A6
Karosseritype		Farve		Reg. dato	27-03-2019
Drivkraft	Diesel	Drivlinje	Front wheel drive	Geartype	Automatisk
KM. stand	150658	Antal nøgler	1	Kontraktnummer	1005604

Udvendige billeder



Fabriksudstyr

Trend	Without first aid box holder	Without additional socket field
Left sliding door	Without cargo area protection set	Without intell. fuse box
Frozen White	Without cargo shelf	Frozen White
Trailer hitch with trailer sway control	Interior handles - 2	Manufacturing plant Otosan (Turkey)
Back-up camera (image displayed on 4" or 8" display)	Without noise protection packages	Without lane change warning system
Airbag* - passenger	O. Stauf. - Dachh.-derf.	Without blind spot information system
All weather tires	Without access ladder	With auxiliary heater/programmable
Remote heater	Without running boards	With auxiliary heater/programmable
Radio with SYNC 3 + Navigation + DAB	With exterior color package 2	Cold start -29 degrees C
Turning lights in headlights	Grill - 3 bar, fully colored	With visibility package basis
Driver-side airbag	Without roof rack	Seat package 15
Anti-lock braking system (ABS)	Gray bodywork part - Gray	Less special value-added packages
Front-wheel drive	Less Rear Window Protector	With low roof
Indicator lights integrated in side mirrors	Without spoiler	Standard panel van
Vinyl flooring in cargo/passenger area	Without rear step	Standard panel van
On-board computer	Without automatic mirror dimming system	With low roof
Electronic brake-force distribution (EBD)	Without passenger seat armrests	With trailer hitch
Electronic stability program (ESP)	With 2-way adj. K. support, front	With Trailer Sway Control (TSC)
Electronic traction control	Table - front seat	With trailer hitch
Hill start assist	Without headrests, rear	With body-colored exterior mirrors
Emergency brake assist	Without rear center armrest	Halogen projection headlights
Crosswind assist	Without rear seat backrest adjustment	With front headlight leveling
Electric windows	Without passenger seat lumbar support	Both elec. extra. ex. mirrors w. Bl.
Generator 220 A	Driver's seat belt warning	Daytime running lights level 2
Cruise control	Without rear seat in the 2nd row	With automatic headlights

Automatic SelectShift transmission (6-speed)	Without rear seat in the 4th row	With additional brake light
Lockable glove compartment	Driver's seat 4-way adjustable seat cushion angle	Only for intermittent wipers front windshield - adjustable
Rear wing doors without glass (opening angle 180 degrees)	Without rear seat packages	With mud flaps, front
Interior filter: pollen filter	Without device dock	With mud flaps, rear
Body/high roof	O. Equip. paket f. fuel saving.	With painted bumpers, front - body color
Body variant: Medium roof	Black exterior door handle	Bumpers rear partially body color
Air conditioning	Rear door / trunk handle ext black	With tinted windows, standard
Adjustable steering column (height/length)	With plastic gear lever knob	With tinted windows, standard
Truck registration	Without fleet key	Only for heated windshield
Model updates	With auto. door lock – Activated	Sync III
Engine 2.0 L - 96 kW TDCi KAT	Less Zonal Opposite Door Relocking	Radio spkr.- 2 low/2 high tone
Parking pilot system	Configurable Unlocking - Conf 1	MFD TFT Touch Screen
Front and rear parking pilot system	Power Lock Group-Speed Dependent	Sync III
Car registration for TRANSIT	Warning light - washer fluid crit.	With on-board computer
Wheelbase 2933 mm	Without Tu-Tone body paint	With navigation system
Spare wheel with road equipment	Without underbody corrosion protection	With navigation system
Particulate filter	Without decorative stripes - body side	Ice Feature Pack 24
Low emissions according to Euro 6d-TEMP	Without hood accent stripes	With rear parking aid
Intermittent windshield wipers, adjustable	Without head protection airbag	With front parking aid
Headlights H4	Without head protection airbag right	With rear parking aid
Sliding door cargo/passenger area right	With front seat belt retractors	With navigation system
Mud flaps front and rear	Without rear seat belts	With speed control system
Side protection moldings	Seatbelt - black	With driver airbag
Visibility package 2	Without Isofix attachment	With passenger airbag
Steel rims 6.5x16	Seatbelt tensioner driver / front passenger	With passenger airbag

Start/Stop system	Without driver / front passenger side airbag.	With deactivation passenger airbag
Partially painted bumpers	Spare wheel release	Grill - rear wall / partition
Style color package	Without tire pressure sensors	Partition with cargo door + window
LED daytime running lights	215/65 R16C 109 T BSW	Floor covering - plastic insert - partial
Trend	Wheel nuts without locking wheel bolts	Cargo area lining - molded part
Cargo/passenger compartment lining: half-height	Without engine speed control	With lockable glove box lid
Fastening eyes (8)	With standard suspension	Cargo area lining - molded part
Lightly tinted heat-insulating glass	With dust shield - brake	Door trim - side/rear - level 1
Central locking with remote control	Axle ratio 3.65	Door trim - side/rear - level 1
Passenger airbag	With mechanical parking brake	Manual control - air conditioning
Fixed towbar	Without collision avoidance system	With pollen filter
Front armrests	Without premium brakes	With circulation heating
Audio navigation system Ford SD (with Ford SYNC 3)	Without rear air control	With auxiliary heater/programmable
Remote control for parking heater / auxiliary heater	Without ventilation system	With auxiliary heater/programmable
LED cargo area light	Refrigerant - air conditioning R134A	With heated driver's seat
High partition wall behind driver and passenger, with window and load-through option at the bottom	Without additional fuel filler neck	With heated passenger seat
Reversing camera with color display	With simple fuel tank	With manual 2-way pass. seat adj.
Sliding door cargo/passenger area left	Fuel inlet without capless w/o flap	W. driver individual s/pass. d. seat n / r
Seat Package 9/15 Driver's seat (adjustable in 4 ways) - Passenger double seat including seat heating, fabric	With diesel switch possibility	With manual lumbar support-driver
Parking heater	Fuel filler neck with lock	With driver seat armrests
Capitol/City Ebony	Electronic speed limiter	Without rear seat in 3rd row
Without underbody protection	Without distance sensor - speed control	With central locking
Without roof conversion	Without rear interior heater	With central locking

Without load securing equipment	With simple instrument panel	Remote entry door - 2 Fob
Mini-Media-Hub (2xUSB) Adp BSL+BT	With speedometer (km/h)	Two-stage entr. system - door
With unobstructed side door opening	Without tachograph	Two-stage entr. system - door
Without foldable step. stl. load door	Electric dual-tone horn	Remote entry door - 2 Fob
LESS MANUAL REGEN INITIATION	Vehicle emergency system	With 180° cargo door stoppers
Without tailgate	Without warning/reverse gear	With rear doors
With standard permissible gross weight	Without driver impairment monitoring	Without rear window
Without special equipment set	Less Mass Movement Sensor	Without rear wiper/washer
Complete vehicle	Without lane keeping aid	With rear doors
Without equipment marketing preparation	Without speed sign recognition	With double side cargo doors
Without special paintwork	Without theft alarm system	With double side cargo doors
Without SVO application/sticker	Without vehicle tilt detection	With cargo area lighting
Less Diagnostic Maintenance Monitor	Without lateral parking aid	Without rearview mirror
Without equipment RSO	Without automatic parking aid	Unbel. sun visor - driver's side
Paintwork solid	Less deep discharge batteries	Sun visor r unlit mirror
Without SVO except packages	With standard power alternator	8 tie-down loops - cargo area
Without stickers - VP application	Without A/V connection	8 tie-down loops - cargo area
Without certification stickers	MM system dual/5th chan./TMC/DAB/Pd	Rear view camera, fixed
Without fire extinguisher mounts	ICP - Mini electronic trim	Rear view camera, fixed
With tool kit	Without mobile phone interface	With anti-lock braking system & ESP+
Without set	Microphone	6.5 x 16" steel wheel
Without tire repair kit	Rd. Bed. - Steering wheel - Frnd. m. PTT	With full wheel cover
Fe.-heb. v.1 Quick act.n. dr.	Voltage output	With steel spare wheel
O. side window in 2nd row, right	Without power socket	With leather-wrapped steering wheel
O. side window in 2nd row, left	Without power socket - rear	With man. adj. - steering column
O. side window in 3rd row, right	Without safe box	With anti-lock braking system & ESP+
O. side window in 3rd row, left	With quad headlights	LHD FWD
Without heated rear window	Fog lights - cornering light	High performance battery
Without console ashtray	Warning reflectors corner rear door	High performance battery

With small roof console	Without light packages	High performance battery
Interior color Dark Palazzo Grey	Without interior lights	6-speed automatic transmission 6F55
Interior color - Ebony	With footwell lights	With diesel particulate filter
Without storage - headliner	With ceiling-mounted interior/map lights	Emission standard stage VI, LNFZ 3
Interior accent package B	Without overhead reading lights rear	Starter - stop/start system
Without sun visors	Without roof-mounted turn signals	2.0 EcoBlue B
With partial headliner - molded part	Without headlight level regulator	Without speed control
Without rear coat hooks	Without programmable interface module	Marketing level 4
Without grab handle - B-pillar	Without battery cutoff relay	With trailer hitch
Without rear ceiling storage compartment	Without wiring harness	
Without cargo net set	Without wiring f. roof beacon	

Dæk og mønster

Position	Mærke	Størrelse	Slidbane	Dæktype
Venstre, For	Michelin	215/65-16	05 mm	Helårs
Venstre, Bag	Goodyear	215/65-19	05 mm	Helårs
Højre, Bag	Goodyear	215/65-16	05 mm	Helårs
Højre, For	Michelin	215/65-16	05 mm	Helårs

Ekstra hjul

Ekstrahjul tilstede

Nej


Position	Mærke	Dæktype
Ekstrahjul		

Reservedæk og rep. kit

Rep. kit tilstede Findes ikke Reservehjul tilstede Ja

Position	Mærke	Størrelse	Slidbane
Reservehjul		/-	


Præsentationsbilleder



Mangler / Tilstand


Ref	Sted	Del	Type	Handling
#1	Nøgle		Ikke tilstede	K5
#2	Mellem folie			

1




Sted Nøgle
 Del
 Type Ikke tilstede

2



Sted Mellem folie
 Del
 Type

2A



Sted Mellem folie
 Del
 Type

Skader

Ref	Sted	Del	Type	Handling
#1	Forrude		Stenslag	K4
#2	Interiør	Sædebetræk, Venstre For	Hul	K5



1

Sted Forrude
 Del
 Type Stenslag



1A

Sted Forrude
 Del
 Type Stenslag



1B

Sted Forrude
 Del
 Type Stenslag



2

Sted Interiør
 Del Sædebetræk, Venstre For
 Type Hul



2A

Sted Interiør
 Del Sædebetræk, Venstre For
 Type Hul

Evt. Mekaniske fejl

Bemærkninger vedr. mekaniske fejl

Service lampe lyser.