

Date 26-03-2025 10:34 Inspection no. 53601 Performed LMH Department FDM Test & Bilsyn Roskilde

TILSTANDSRAPPORT

Stamdata

Registreringsnummer	DH52794	Stelnummer	WF0JXXWPCJJA47550		
Mærke	FORD	Model	S-MAX	Version	EcoBlue 2.0 (190HK) MPV FWD A8
Karrosseritype	Stationcar	Farve	Sort	Reg. dato	29-03-2019
Drivkraft	Diesel	Drivlinje	Front wheel drive	Geartype	Automatisk
KM. stand	210169	Antal nøgler	2	Kontraktnummer	7024233

Udvendige billeder









Date 26-03-2025 10:34 Inspection 53601 LMH FDM Test & Bilsyn

no. Performed by Department

Roskilde



Fabriksudstyr

Rear lights - LED hi.
With additional brake light
With Adaptive
Lightining
Daylight Stage 2
With headlamp washer system
With windshield
wipers auto.
With bright door frame trim
Front Bumper - Mic Black
Contrast color, rear impact bar
Front Bumper - Mic Black
Contrast color, rear impact bar
With tinted glazing
With laminated windshield
Only For Heated Windscreen
Only For Heated Rear Screen
AM/FM/DAB-Antenna
With 8 Speakers
Sync III
- With Delay Lighting Interior
With On-board
computer With On-board
computer
MFD TFT Touch Screen
With Parallel Parking Assistant

Assistant

Without luggage net luggage compartment With luggage compartment cover

> Without noise protection packages

> > Without interior partition

Grill lower surr. high gloss black

Without roof rack

Lower side moulding single color black

Without spoiler

With driver seat backrest pocket Passenger seat backrest pocket Less Passenger Seat **Cushion Ext** LESS DRIVER SEAT CUSHION EXTEN

With 2-way Adj. Frnt Headr. Restraints

With Manual Driver Seat

With Manual Passenger Backrest Adj. Sec Row Fore-Aft Adj Seat Track Without Multicontour

Seats Without Rear Seat Heater

> Beltwarn. D/P/2/3 EU TL/SD Without Rear Seat

Comfort pack

Without Trailer hitch

With Front Tow hook

With Rear Tow hook

Travel package 3rd row - 2 individual seats with Easy Fold Flat Active cruise control with Stop&Go for automatic transmission Business package Metallic color Shadow Black 2nd row with 3 individual seats (FoldFlatSystem) Active noise compensation Ambient lighting in front (LED) Anti-lock braking system (ABS) Traction control system (ASR) Drive type: front-wheel drive Electrically folding exterior mirrors Electrically adjustable and heated exterior mirrors Exterior mirrors in body color Turn signal in exterior mirrors Footwell lighting in exterior mirrors On-board computer Dual end-pipe exhaust system Electronic brake-force distribution Electronic stability program (ESP) Hill-start assist system (Hill-Holder) High-beam assist (automatic headlight dimming)

S-MAX Titanium



FDM Test & Bilsyn

Inspection Performed

Date

no

by

LMH

53601

Department

Roskilde

With Rear Parking Aid

With Front Parking Aid

With Rear Parking Aid

ICE Feature Pack 53

With Navigation system Tire pressure monitors - 433 Mhz

Knee pad - driver

Adap. Sp. Cont. with CADS III

> Intelligent speed assistance

With intelligent driver airbag With intelligent driver airbag With side airbag driver side With side airbag passenger side With passenger airbag deactivation

> Console - with closed storage

> > With Sun Visors

With small overhead console

> Front floor mats luxury carpet

Rear floor mats luxury carpet

Front floor mats luxury carpet 2-Zone climate control with auto. temp. adjustment

Pollen/carbon filter

With circulating heater

Engine cover - engine bay

> Electric automatic shift

M Komf-Open/Close -Dr/SI.Ds.-Lk.

Frequency 433 MHz

Without remote entry

Krftfuel inlet w cap lock w locking M. 2x Heated rear window wiper/washer

> Without heated washer nozzle

Without Underbody corrosion protect.

Sensor - Front Bumper

With Front License Holder Rear Bumper Load Protector - Black Without Restraint Systems Without Inflatable **Knee Bolster-Pass** LH Side Impact airbag - Level 2 RH Side Impact airbag - Level 2 Without Rear Seat Side Airbag

> Without rear safety belt tighteness

With Man adjust Sec Row/3rd Row Belts

With extnd. Adj Front safety belt.

> With Auto lock w Crank force limit

With Std. Rear Shocks (NO NIV) NO

17x7.5 in All Wheels Type 4



Emergency brake assist Lane keeping assist with driver fatigue detection sensor Color display for onboard computer (10inch) Electric windows front + rear with comfort closing Window frames with chrome trim Laminated windshield Premium floor mats Luggage compartment cover/roller blind Automatic transmission - Type: 8F40 (8-speed) Intelligent Protection System (IPS) Isofix mounts for child seats Body: 5-door KeyFree system Electric child lock 2-zone automatic climate control Lumbar support front left seat Lumbar support front right seat Leather steering wheel with multifunction Steering column (steering wheel) height/length adjustable Reading lights in the rear Alloy wheels Front center armrest with storage compartment and 12V

outlet

EcoBlue KAT

Engine 2.0 L - 140 kW

FDM Test & Bilsyn

53601

LMH

Roskilde

Department

Date

no. Performed

by

Inspection

With additional heater

With additional heater

Heated driver seat var. Temp. With Heated passenger - var.

Temp.

Front sports seat

Front sports seat

With driver 4-way adj. seat

With manual 4-fach adj. passenger seat

With driver 4-way adj. seat

With manual 4-fach adj. passenger seat

With manual driver lumbar support With manual passenger lumbar support

> With split folding rear seat bench (60/40) With foldable seat in

With manual backrest adjustment rear seat

3rd row

Second row of seats -3 individual seats Second row of seats -3 individual seats With headrest center rear With headrest center rear Power front windows

Power front windows with one-touch function Rear pow.window lift/low. Rear pow.window lift/low. Rear pow.window lift/low. Power front windows with one-touch

function

Without Spare Wheel

With Std Front Tread Tire

With Std rear Tread Tire

With Black center Wheel Cap

Locked wheel nuts With speed limiting

device

Cold start -29 deg C

Without Block Heater

Without Remote Start

With Front Stabilizer

With Rear Stabilizer

3.17

Muffler Double Exhaust With 17in - Front ventilated, rear unventilated rotor With Unpainted brake caliper Brakes-ABS+ESP/RSC/TSA Less Assembly Plant Fuel Fill Without air cleaning sensor Without rear climate control

GWP less than 150

With Clean Fuel Fleet vehicle Without Water separator With Diesel switchable option

Standard Pedal Design



My Key (2nd programmable vehicle key)

Ford navigation module (in addition to audio system)

Electric parking brake

Front and rear park assist system

Power KeyFree start function

Tire repair kit

Tire pressure monitoring system

Particulate filter

Low emission according to emission standard Euro 6 Low emission according to emission standard Euro 6d-TEMP

Rain-sensing wipers

Headlights with delayoff function

Headlight assistant with day/night sensor

Electric power steering

Front seats adjustable (4-way)

Front sports seats

Start/stop system

Storage compartment under front left seat Storage compartment under front right seat

LED daytime running lights

Warning system for rear seat belts

Warning system for front seat belts

Winter package

Central locking with remote control



53601

LMH

Department

Date

no. Performed

by

Inspection

FDM Test & Bilsyn Roskilde

> Electric door lock with remote unlocking

Electric door lock with remote unlocking

> Passive keyless entry/start

Passive keyless entry/start

My Key

Body-colored exterior door handle Body-colored exterior door handle Body-colored exterior door handle With bright door frame trim Seat belt tensioner driver/passenger seat Interior. Ambient LED Interior roof light LED Humidity sensor Sun Visor I. illuminated mirror Sun Visor r. illuminated mirror With Immobilizer integrated With Immobilizer integrated Power socket 230 V Cup holder (2) - row 1 Table - front seat Rotary shifter With Isofix attachment With storage under seat - passenger With storage under the driver's seat Rear view camera. fixed

With brake assist

With brake assist

Electronic Steering Column Lock

> Entf.sensorspd.control

Herk. Kmb.instr. hybr. m. TFT-Disp.

> With speedometer (km/h / mph)

7000 RPM Tachometer Two-tone horn electric, Level 2

With Compass Display

Without Acustic SPD Warn Human-Machine Interface 4 Without Anti-theft alarm Voltage Regulator-12V Socket MM-System Dual/5. Kan./TMC/DAB/Pd Without Radio Interference Without entertainment system Without Mobile phone interface Without wireless charging Without Radio Control - Rear seat Without Garage Door Opener Without Socket With 2 Additional Power Points Rear Without Front Video Camera Without Aero Equipment With Halogen Headlights Without High beam headlights Without Light Packages With front and rear reading lights With glove box lighting



3rd row with individual seats, foldable (Easy FoldFlatSystem, FFS) Adaptive cruise control (Adaptive Cruise Control / ACC) Business package 3 Folding table integrated in driver and passenger seat backrest Paintwork Iridium Black Mica Headlight cleaning system (SRA) Sunshades on rear door windows 230V power socket Axis Omni fabric/Ebony Without roof conversion With standard B-pillar trim Without rear mud flaps Without interior package Without front mud flaps Rear door, passenger side Without luggage compartment mat With manual tailgate Not a special utility vehicle Built in Valencia factory Calculate GVW Or Pick Frm Table Without equipment marketing preparation Without sales emblem Without special paintwork Without electronic equipment Marketing level 1 Without RSO equipment Without equipment

for warm weather

53601

LMH

FDM Test & Bilsyn Roskilde

Performed by Department

Date Inspection

no.

With electric parking brake

CADS-Gen3 Package Collision avoidance system No. 2 CADS-Gen3 Package Collision avoidance system No. 2 Traffic sign recognition Adaptive cruise control with CADS III Collision avoidance system No. 2 Lane keeping assistant Lane keeping assistant Adaptive cruise control with CADS III Tire repair kit Without spare wheel With leather-covered steering wheel With leather-covered steering wheel With leather-covered steering wheel With manual adj. steering column With manual adj. steering column Select-Shift-Techn. with steering column control With electric power steering LHD FWD With hill start assist Automatic transmission - 8F40

Emission standard Euro 6.2 Starter - stop/start system

CVH 1.4 CFI (71PS)

(-) SVP

Without luggage
compartment lighting
Without Door Sill Lights
Without heated
steering wheel
Without special
equipment set
Without Vehicle
Emergency System
Without Blind Spot
Information System
With Standard
Suspension
Without Spare wheel
carrier
5-Door-SAV
Iridium Black Metallic
Iridium Black Metallic
Active grille shutters
With bright door frame trim
Front door entry sill - Silver logo
Without trailer hitch
With Diversity Antenna
El.adjust.heated Fold. Ingr/exp.
With body-colored exterior mirror
0. External
appearance package
With Adaptive
Lightining
With front headlamp
levelling
With fog lamps
With fog lamps
With fog lamps
With black fog lamp cover
With automatic high
with automatic high
beam headlights



Without SIP

Without SIP
Body paint - Solid color
Without carline
emblem
Without SVO except
packages
Without stickers - VP
application
Without tailgate emblem
Without special
language stickers
Without water fording
equipment
LESS MARKETING
COMFORT PACK
Without fire
extinguisher
attachments
"D" Pillar Moulded Trim
"A" Pillar Cloth Trim
"C" Pillar Molded Trim
With fixed rear side windows
Less Grille-Upper
Front windows
Toughened glass
Without center
console ashtray
With standard
dashboard
With glove box cover
Without Kit - floor mats
Fixed pedals
Interior accent package L
With fabric headliner
With door trim, level 1
With Level 3 Quarter Trim Panel
Without luggage compartment floor net set
4 luggage

compartment loops



Date	26-03-2025 10:34
Inspection no.	53601
Performed by	LMH
Department	FDM Test & Bilsyn Roskilde

Dæk og mønster

Position	Mærke	Størrelse	Slidbane	Dæktype
Venstre, For	Continental	235/55-17	02 mm	Sommer
Venstre, Bag	Continental	235/55-17	02 mm	Sommer
Højre, Bag	Continental	235/55-17	05 mm	Sommer
Højre, For	Continental	235/55-17	05 mm	Sommer

Ekstra hjul

Ekstrahjul tilstede	Nej		
Position	Mærke	Dæktype	
Ekstrahjul			

Reservedæk og rep. kit

Rep. kit tilstede		Ja	Reservehjul tilstede		Ikke relevant
Position	Mærke		Størrelse	Slidbane	
Reservehjul			/-		



Date 26-03-2025 10:34 Inspection no. 53601 Performed by LMH Department FDM Test & Bilsyn Roskilde

Præsentationsbilleder





Date	26-03-2025 10:34	
Inspection no.	53601	
Performed by	LMH	
Department	FDM Test & Bilsyn Roskilde	

Mangler / Tilstand

Ref	Sted	Del	Туре	Handling

Skader

Ref	Sted	Del	Туре	Handling
#1	Forrude	Rude	Revne	K5
#2	V. bagskærm	Skærm	Bule(r)	K4
#3	H. forskærm	Skærm	Rids	K3



Sted	Forrude
Del	Rude
Туре	Revne



Sted	Forrude
Del	Rude
Туре	Revne





Date	26-03-2025 10:34
Inspection no.	53601
Performed by	LMH
Department	FDM Test & Bilsyn Roskilde



Sted	V. bagskærm
Del	Skærm
Туре	Bule(r)



Sted	V. bagskærm
Del	Skærm
Туре	Bule(r)



Sted	H. forskærm
Del	Skærm
Туре	Rids



Sted	H. forskærm
Del	Skærm
Туре	Rids

Evt. Mekaniske fejl

Bemærkninger vedr. mekaniske fejl

