

Department

54583

31-03-2025 12:16

ATN

FDM Test & Bilsyn Holstebro

TILSTANDSRAPPORT

Stamdata

Registreringsnummer	CJ29297	Stelnummer	WF0JXXGAHJKK04233		
Mærke	FORD	Model	FIESTA	Version	1.0 EcoBoost (125 HK) 5-dørs FWD M6
Karrosseritype	Hatchback	Farve	Rød	Reg. dato	12-04-2019
Drivkraft	Benzin	Drivlinje	Front wheel drive	Geartype	Manuel
KM. stand	114585	Antal nøgler	2	Kontraktnummer	1008489

Udvendige billeder













Department

54583

Holstebro

ATN FDM Test & Bilsyn

31-03-2025 12:16

Fabriksudstyr

Titanium	Without roof rack	With rain sensor windscreen
Race Red	Without exterior sill covers	With heated washer nozzles
Comfort Package 2	Without door edge guards	With man-controlled rear wiper/washer
Cruise control	With driver's backrest pocket	Molded part exterior frame black/light
Rain sensor	Passenger seat back pocket	With rear spoiler
Passenger airbag deactivation	With fixed passenger seat	With rear spoiler
Ambient lighting front (LED)	Without fold/slide driver's seat	With rear spoiler
Anti-lock braking system (ABS)	Without driver's seat armrests	With rear spoiler
Electrically adjustable and heated exterior mirrors	With 2-way adj. driver lumbar support	With plastic rear bumper - two-pc.
Exterior mirrors in body color	With fixed rear seat cushion	With tinted windows, standard
Turn signal integrated in exterior mirrors	Without passenger seat lumbar support	Acoustic windscr. (laminated glass)
On-board computer	With manual 2-way passenger seat adj.	Only For Heated Windshield
Glasses compartment integrated in headliner / roof console	Without tow bar	Multimedia system equipment 54
Cool & Sound package	Without preparation for towing	With radio controls on steering wheel
Fabric headliner	Standard engine power	With 6 radio speakers
Roof spoiler in body color	Without device dock	Vehicle emergency system
Electronic brake force distribution	Shift lever boot leather	With onboard computer
Electronic Stability Program (ESP)	With child safety lock	With onboard computer
Energy regeneration (Smart Regenerative Charging)	Without Ford Key Free system	MFD TFT Touch Screen
Hill-start assist	With roof in body color	Tire pressure sensors - 433 Mhz
Emergency brake assist	Without body stripe - body color	Tire pressure monitoring Version II
Lane-keeping assist	Front bumper, body contrast color	With dash panel upscale design
Front electric windows with comfort operation	Without front license plate bracket	Exclusive Pack 2
Velour floor mats - 2nd row	Without energy-absorbing bumper reinforcement	Speed control and ASLD
Velour floor mats - front	Without inflatable knee bolster - driver	Speed control and ASLD





Department

31-03-2025 12:16 54583

ATN

FDM Test & Bilsyn Holstebro

Speed limiter	Head protection airbag left	With driver airbag
6-speed transmission	Head protection airbag right	With passenger airbag
Leather handbrake lever	Without rear side airbag	With driver airbag
Interior filter: Dust and pollen filter	Without knee airbag - driver side	With passenger airbag
Intelligent Protection System (IPS)	S-Belts rear-2. row active outer	With driver side airbag
Isofix child seat anchor points	With man. adj. rear headrests	With passenger side airbag
Body: 5-door	Lashing eyes Style 1	With passenger airbag deactivation
Mechanically adjustable rear headrests (3 pieces)	Without spare wheel	Center console w. armrest (entire)
Leather steering wheel	With plastic wheel hub cover	Center console w. armrest (entire)
Adjustable steering column (height/length)	Without wheel covers	With luggage compartment cover
Reading light front	Wheel nuts without locking system	Deluxe headliner
Alloy wheels	With standard profile - Any	Refrigerant - A/C HF01234YF
Front armrest with storage compartment and 12V socket	Parts only for light alloy wheels	With pollen filter
Center console with armrest	Without engine speed control	With pollen filter
Engine 1.0 Ltr 92 kW EcoBoost	Starter interlock/clutch pedal	With circulating heater
My Key (2nd programmable vehicle key)	3.94	With additional heater
Fog lights with static cornering light	Without tailpipe extension	With additional heater
Petrol particulate filter (OPF)	With unpainted brake calipers	With heated driver's seat
Tire repair kit	3.42/1.96/1.28/0.94/0.76/0.63	With heated passenger seat
Tire pressure monitoring system	Without gear shift with automatic shift	Sports seat front
Particulate filter	For unleaded fuel	Sports seat front
Split rear seat	For fuel with 95 octane	With man. 4-way adj., driver's seat
Folding rear seat backrest	Fuel filler door with lock	With man. 4-way adj., driver's seat
Low emissions according to exhaust standard Euro 6	Standard pedal design	With man. Driver lumbar support
Low emissions according to exhaust standard Euro 6d- TEMP	Without electronic speed limiter	With split folding rear seat
Headlights with delay function	Analog instruments medium design	With split folding rear seat





Department

54583

ATN

FDM Test & Bilsyn Holstebro

31-03-2025 12:16

Projection lens design headlights	With speedometer (km/h)	With folding seat in 2nd row
Headlight assistant with day/night sensor	Electric two-tone horn	With 2-way adj. passenger lumbar
Electric power steering	Without driver impairment monitoring	support With 2-way adj. passenger lumbar
Height-adjustable driver's seat	Without acoustic speed warning	support With center headrest rear
Left sun visor with mirror	Without speed sign recognition	With center headrest rear
Right sun visor with mirror	Without theft alarm system	El. front windows w. single-touch
Sports seats front	Without automatic parking assist	El. front windows w. single-touch
Bumper in body color	Without additional CD player	Window Pack 4
Exterior door handles in body color	ICE-Low with enhanced connectivity	With central locking
Tinted windows	ICP - Mini Electronic Trim	With central locking
Warning system for rear seat belts	Without radio subwoofer	Remote door opening - 2 folding keys
Remote central locking	Without mobile phone interface	Remote door opening - 2 folding keys
Chrome decor strips below side windows	MGM - Voice Pass Through	With central locking
Cruise control	Without smoker's package	Seatbelt warn. Drv./Psg./2nd R./Eu T&S
Painting Race Red	Without cigarette lighter	Restraint system package 2
Heated steering wheel	Without special equipment packages	Driver/Passenger seatbelt pretensioner
Windshield wipers with rain sensor	With bright fog light surround	Indoor ambient LED
Winter package	Without entry lights	With roof-mount. indoor/karte lights
Domo/Dynamo / Ebony	Without rear parking assistance	With electrochromic rearview mirror
Without roof conversion	Without special equipment kit	With electrochromic rearview mirror
Without rear mud flaps	Without navigation system	With additional socket
Without interior package	Without camera	With leather gear shift knob
Without front mud flaps	Without blind spot information system	With Isofix attachment
Not a special-purpose vehicle	Without front door sill protection	With upscale overhead console
Assembly plant Niehl	With standard suspension	With IVD/traction control/ABS
Without off-road package	Without collision avoidance system	Front and rear disc brakes
Without equipment marketing preparation	Without front parking sensors	Front and rear disc brakes
Without sales emblem	With Visibility package	Electronic Emerg Brake Assist





Department

31-03-2025 12:16 54583

ATN

FDM Test & Bilsyn Holstebro

Without special paintwork	USB 2-accessory inc. iPod function	Cover. Handbrake - black
Without SVO application/stickers	5-door sedan	Lane keep assist
Marketing level 1	Race Red	Lane-keeping assist
Manual air conditioning	Race Red	6.5 x 16" alloy wheel - Type B
Without SIP	Active grille shutters	195/55R16 tires
Exterior paint Uni paint	Grille bars - top chrome high- gloss	Tire repair kit SVC
Fiesta Carline Badge	Both electrically adjustable heated door mirrors with.bl	Without spare wheel
Without cooling equipment	With body-colored exterior mirror	With heated steering wheel
For moderate climates	With headlights - level 2	Steering wheel - 3 spoke, leather
Without SVO except packages	With headlights - level 2	Steering wheel - 3 spoke, leather
Without rear hatch emblem	With cornering lights	With man. adj steering column
Less Marketing Driver Assist Pack	With front headlight leveling	With man. adj steering column
Sun visors Indiv. III. w. Mirr.	Both electrically adjustable heated door mirrors with.bl	With IVD/traction control/ABS
Without perimeter/auto. locking function	With fog lights	With IVD/traction control/ABS
Man. act. side wind. rear wind.	With fog lights	With IVD/traction control/ABS
Without center console ashtray	With fog lights	LHD FWD
With door trim, level 2	With automatic headlight adjustment and wiper	With hill start assist
Less Rear Seat Ash Tray	Tail lights - LED rear	6-speed manual transmission - 6MX65
Without parcel shelf	With additional brake light	Exhaust standard Euro 6.2
Retention strap - First aid kit	DTRL Lamp Lit In Pos 0 And Pos	Starter - stop/start system
With warning triangle straps	With cornering lights	1.0L EcoBoost 120PS/125PS/140PS
Rear Door Trim Panel - Cloth	DTRL Lamp Lit In Pos 0 And Pos	(-) SVP

Dæk og mønster

Position	Mærke	Størrelse	Slidbane	Dæktype
Venstre, For	Bridgestone	195/55-16	05 mm	Vinter
Venstre, Bag	Bridgestone	195/55-16	03 mm	Vinter





Department

by

54583

Holstebro

ATN FDM Test & Bilsyn

31-03-2025 12:16

Højre, Bag	Bridgestone	195/55-16	03 mm	Vinter	
Højre, For	Bridgestone	195/55-16	05 mm	Vinter	

Ekstra hjul

Ekstrahjul tilstede

Nej

Position	Mærke	Dæktype
Ekstrahjul		

Reservedæk og rep. kit

Rep. kit tilstede Ja Reservehjul tilstede Ikke relevant

Position	Mærke	Størrelse	Slidbane	
Reservehjul		/-		





Department

by

54583

31-03-2025 12:16

ATN

FDM Test & Bilsyn Holstebro

Præsentationsbilleder





















Date 31Inspection no.
Performed by
Department FDM

31-03-2025 12:16 54583

ATN


FDM Test & Bilsyn Holstebro

Mangler / Tilstand


Ref Sted Del	Туре	Handling
--------------	------	----------

Skader

Ref	Sted	Del	Туре	Handling
#1	Forrude	Rude	Stenslag	K4
#2	Motorhjelm	Hjelm	Stenslag	K2
#3	H. bagdør	Dør	Rids	K3
#4	H. A-stolpe	Stolpe	Ridser	K4









Sted	Motorhjelm
Del	Hjelm
Туре	Stenslag



Date 31-03-2025 12:16
Inspection no. 54583
Performed by ATN
Department FDM Test & Bilsyn Holstebro




Sted	H. bagdør
Del	Dør
Туре	Rids



Sted	H. bagdør
Del	Dør
Туре	Rids



Sted	H. A-stolpe
Del	Stolpe
Туре	Ridser



Evt. Mekaniske fejl

Bemærkninger vedr. mekaniske fejl