

TILSTANDSRAPPORT

Stamdata

Registreringsnummer	CP85916	Stelnummer	WBA71AC05L5P95497		
Mærke	BMW	Model	X1	Version	18d SUV sDrive
Karosseritype	Stationcar	Farve	Hvid	Reg. dato	02-03-2020
Drivkraft	Diesel	Drivlinje	Front wheel drive	Geartype	Automatisk
KM. stand	164907	Antal nøgler	2	Kontraktnummer	7238862

Udvendige billeder



Fabriksudstyr

Error: No response from service. Try again or contact support.

Dæk og mønster

Position	Mærke	Størrelse	Slidbane	Dæktype
Venstre, For	Michelin	225/55-17	05 mm	Vinter
Venstre, Bag	Michelin	225/55-17	07 mm	Vinter
Højre, Bag	Michelin	225/55-17	07 mm	Vinter
Højre, For	Michelin	225/55-17	05 mm	Vinter

Ekstra hjul

Ekstrahjul tilstede Ja





Position	Mærke	Dæktype
Ekstrahjul		

Reservedæk og rep. kit

Rep. kit tilstede Ikke relevant Reservehjul tilstede Nej

Position	Mærke	Størrelse	Slidbane
Reservehjul		/-	

Præsentationsbilleder



Mangler / Tilstand

Ref	Sted	Del	Type	Handling
-----	------	-----	------	----------

Skader

Ref	Sted	Del	Type	Handling
-----	------	-----	------	----------

Evt. Mekaniske fejl

Bemærkninger vedr. mekaniske fejl