

Date 07-05-2025 13:58 Inspection no. 63324 Performed by RSJ Department FDM Test & Bilsyn Odense

TILSTANDSRAPPORT

Stamdata

Registreringsnummer	CJ85305	Stelnummer	WF0XXXTTGXKD76751		
Mærke	FORD	Model	TRANSIT	Version	2.0TDCi - 4WD (170 HK) Kassevogn AWD M6
Karrosseritype		Farve		Reg. dato	30-04-2019
Drivkraft	Diesel	Drivlinje	4 wheels drive	Geartype	Manuel
KM. stand	72816	Antal nøgler	2	Kontraktnummer	1003057

Udvendige billeder











Date	07-05-2025 13:58
Inspection no.	63324
Performed by	RSJ
Department	FDM Test & Bilsyn Odense

Dæk og mønster

Position	Mærke	Størrelse	Slidbane	Dæktype
Venstre, For	Continental	235/65-16	07 mm	Vinter
Venstre, Bag	Goodyear	235/65-16	06 mm	Vinter
Højre, Bag	Goodyear	235/65-16	06 mm	Vinter
Højre, For	Continental	235/65-16	07 mm	Vinter

Ekstra hjul

Ekstrahjul tilstede	Nej		
Position	Mærke	Dæktype	
Ekstrahjul			

Reservedæk og rep. kit

Rep. kit tilstede		Findes ikke	Reservehjul tilstede		Nej
Position	Mærke		Størrelse	Slidbane	
Reservehjul			/-		



Date 07-05-2025 13:58 Inspection no. 63324 Performed RSJ Department FDM Test & Bilsyn Odense

Præsentationsbilleder

















8









Date	07-05-2025 13:58
Inspection no.	63324
Performed by	RSJ
Department	FDM Test & Bilsyn Odense

Mangler / Tilstand

Ref Sted	Del	Туре	Handling
Skader			
Ref Sted	Del	Туре	Handling

Evt. Mekaniske fejl

Bemærkninger vedr. mekaniske fejl

Fabriksudstyr

Without safe box	Interior color - Charcoal Black	Trend
Without dual rear tire package	With storage - roof lining	Left sliding door
With halogen headlights	Interior trim accents package B	High roof (H3)
Less roof marker/clearance light	With partial headliner - molded part	Mud and Snow tires
Warning reflectors corner rear door	Left sun visor without mirror	Seat package 2
Without cornering lights	Right sun visor without mirror	Trailer hitch with trailer sway control
With footwell lights	Without rear coat hooks	Frozen White
With roof-mounted interior/map lights	Without grab handle A-pillar	2nd battery
Without overhead reading lights rear	Without rear overhead storage compartment	3rd brake light
Without glove box lighting	With cargo tie-down strap	Turning light in headlight

07-05-2025 13:58

63324

RSJ

Department

Date

no

by

Inspection

FDM Test & Bilsyn Odense

Performed

Without side marker lights

Without roof-mounted turn signals

With rear fog lights

Without rear position lights Without headlight adjuster Without programmable interface module

> Without battery cut-off relay

> > Without wiring harness

Without additional roof beacon wiring

Without intelligent fuse box

Frozen White

Manufacturing plant Otosan (Turkey)

Without camera

Without lane change warning system

Without media data interface module

Programmable fueladditional heater Cold start -29 degrees С

With visibility package base

Standard panel van

With high roof

Standard panel van

With high roof

With high roof

With high roof

Without handle for first aid kit

Without luggage compartment protection set

Without cargo shelf

Without luggage area tie-downs Without interior grab handles

> Without interior partition

Glasses compartment - roof - driver's side

Without access ladder

Gray grille

Gray body-colored trim part

> Less rear window protector

Without side auxiliary step Large mirror head/Short base Without automatic mirror tilt system With 2-way adjustable driver's seat support, front Without table - front seat Without rear headrests Without rear seat armrest Without rear seat backrest adjustment

> Without 6th row of seats

> > Driver's seat belt warning

Without rear seat in 2nd row Without rear seat in 4th row Without fifth row of seats



Storage compartment in roof lining of driver's cab

Driver's side airbag

Anti-lock braking system (ABS)

Traction control (ASR)

Drive type: all-wheel

drive Audio system: Radio/CD player with multi-function display Exterior mirrors electrically adjustable and heated Turn signal integrated in exterior mirror Floor covering: Vinyl in cargo/passenger compartment

On-board computer

Roof lining in the passenger compartment

Tachometer

Electronic brake-force distribution (EBD) Electronic stability program (ESP)

> Hill-start assist system

Electric windows

Generator 165 A

Cruise control

Transmission 6-speed

Handle on B-pillar

Rear wing doors without glazing (opening angle 180 degrees) Heating with recirculation switch Interior filter: Pollen filter

Body: Box high roof

Date 07-05-2025 13:58 Inspection no. Performed by

RSJ FDM Test & Bilsyn

63324

Department

Odense

With high roof

With trailer hitch

With trailer hitch

With Trailer Sway Control (TSC)

With trailer hitch

Roof-mounted radio antenna

With headlight range adjustment front Both electrically adjustable exterior mirrors with heating

With fog lights

With daytime running lights With automatic headlights Headlights statically swivelable With additional brake light Intermittent windshield wipers only - adjustable

With rear mudflaps

Front bumper partially body colored

With standard tinted windows With standard tinted windows

For heated windshield only

ICE Mid Audio (1C) with connectivity Ice function package 2 With radio controls on steering wheel Radio speakers-2

low/2 high

Without 3-seater 2nd row against direction of travel Driver's seat 4-way adjustable seat cushion angle Passenger seat 4-way adjustable seat cushion angle Without rear seat packages Alternative rear axle A Less emergency hammer Without fuel efficiency package Black exterior door handle

Exterior grab handle black With plastic gearshift knob

Without fleet key

With auto door locking - enabled Less zonal opposite door relocking

> Configurable unlocking - Conf 1

Power lock groupspeed dependent

Without Ford Key Free system

Without rear window wiper/washer Without headlight washer

Warning light - washer fluid level

Without rear sunroof

Without underbody corrosion protection Without body side moldings Rear bumper plastic unpainted



Body variant: Medium high roof Air conditioning Silver radiator grille High partition wall behind driver and front passenger

> Steering wheel (leather) Steering column (steering wheel) height/length adjustable Headlight range control

Truck registration

Engine 2.0L - 125 kW TDCi KAT Front and rear park assist Production plant: Otosan

Wheelbase 3300 mm

Wheel covers

Particulate filter

Low emissions according to Euro 6 emission standard

Sliding door cargo/passenger area right Wide side protection moldings

Power steering

Seats in cargo/passenger compartment: 1st row, 3-seater bench

Steel wheels 6.5x16

Partially painted bumpers

Daytime running lights

Trend

Date 07-05-2025 13:58 Inspection no. Performed by

FDM Test & Bilsyn Odense

Department

With A/V socket

63324

RSJ

With on-board computer

> With rear parking assist

With front parking assist

With rear parking assist With speed control system

With driver airbag

Grille - rear wall/partition Floor covering partially plastic Cargo area trim molded part With grab handle - Bpillar

> With lockable glove hox lid

> > Cargo area trim molded part

Door trim - side/rear -Level 1

Door trim - side/rear -Level 1 Programmable fueladditional heater Manual control - air conditioning With pollen filter With recirculation heating Programmable fueladditional heater Programmable fueladditional heater Programmable fueladditional heater With heated driver's seat With heated passenger seat

Standard front seats

Without rear bumper undershield Without front license plate bracket Without front bumper undershield Without head protection airbag Without right head protection airbag Without warning safety features With front seat belt retractors

Without rear seat belts Without passenger airbag

Black seat belt

Without deactivating passenger airbag

> Without Isofix attachments

Driver's seatbelt tensioner

Without driver/passenger side airbags

Without spare tire unlock Without side underbody rails Without tire pressure sensors Without spare tire lock With single rear tires Wheel nuts without wheel lock Without engine speed control Standard electric starter

With dust shield brake

4.10

With left and right exhaust pipe



Integrated rear step

Tinted windows

Interior trim in cargo/passenger compartment: halfheight

Immobilizer

Central locking with remote control Second remote key foldable Front axle load increase to 1.85 t Trailer hitch: fixed ball head

Cold start package

Cargo area LED light

Tire repair kit

Sliding door cargo/passenger area left

Visibility package 1

Seat package 14: driver's seat (4-way adjustable) - single passenger seat (4-way adjustable) including seat heating, fabric

Stand heater

Lane/Max Charcoal Black
Without underbody protection
Without roof conversion
Less D pillar assist handle
Without accessory USB unit
Without mud flaps, front
Without particulate filter
With hill-start assistant
Full front with windshield and seat recess
With unrestricted side door opening

07-05-2025 13:58

63324

RSJ

Department

FDM Test & Bilsyn Odense

Date

no. Performed

by

Inspection

With manual driver lumbar support With manual passenger lumbar support With driver's seat armrests With passenger seat armrest Without 3rd row of seats Electric front windows with one-touch function With central locking With central locking Remote key entry - 2 Fob Two-stage entry system - door Two-stage entry system - door Remote key entry - 2 Fob

With rear doors

With rear doors

With double side cargo doors With double side

cargo doors With cargo area lighting

Without interior mirror

With anti-lock braking system & ESP+ Maximum front axle

load

6.5 X 16" Steel wheel

With full wheel cover

Without spare tire

Tire repair kit

With leather-wrapped steering wheel With manual adjustable steering column With anti-lock braking system & ESP+

With mechanical parking brake

Without collision avoidance system

Without brake assistant Without tracking system - FIA

Without transfer case

Without rear climate control

> Without ventilation system

Coolant - air conditioning R134A

Without additional fuel filler openings

With single fuel tank

Fuel inlet without cap without tether With diesel switch capability

Fuel filler with lock

Electric speed limiter

Without rear interior heater With conventional instruments Without resistor combined instruments With speedometer

(km/h)

Without tachograph Electric dual-tone horn Without multifunction display Without navigation system Without navigation data Without vehicle emergency system Without reverse warning Without driver impairment monitoring Without speed sign

recognition



Without foldable step rear load door

Less manual regen initiation

Without 2nd superstructure Without grid bulkhead - 2nd unit Less tailboard support

straps

Less auxiliary I/P console

With standard permissible total weight

Without special equipment kit

Complete vehicle

Without equipment marketing prep

Without sales emblem

Without special paintwork Without SVO application/sticker Less special valueadded packages Without engine equipment group Exterior paint solid paint Without cooling equipment Without SVO except packages Without sticker - VP application Without tailgate emblem Without certification sticker Without SVO marketing packages Less marketing comfort pack Without fire extinguisher mounts Without fire extinguisher

Without tool kit

Without set

Date	07-05-2025 13:58
Inspection no.	63324
Performed by	RSJ
Department	FDM Test & Bilsyn Odense

LHD 4WD

LHD 4WE
High-performance batter
High-performance batter
High-performance batter
6-speed manua transmission - MT82
Emissions standard Stage VI, LNFZ 3
2.0L CR TC Diese Panther C
Without engine speed contro
Marketing Level

With trailer hitch

Without theft warning system	
Without vehicle tilt detection	
Less deep discharge batteries	
With standard power alternator	
Without integrated control unit	
Microphone	
Without voice control modules	
Without MFD controls on steering wheel	
Socket #3	
Without socket	

Without rear socket

Without side windows 2nd row, right Without side windows 2nd row, left Without side windows 3rd row, right Without side windows 3rd row, left Without side windows 4th row, right Without side windows 4th row, left Without rear window Without heated rear window Without console ashtray With standard roof console Interior color - Pewter

TEST & BILSYN

Wefleet