

Date
Inspection
no.
Performed
by

Department

64896

CS

FDM Test & Bilsyn Ballerup

17-05-2025 12:15

TILSTANDSRAPPORT

Stamdata

Registreringsnummer	CS39375	Stelnummer	WF0JXXGAHJJA48348		
Mærke	FORD	Model	FIESTA	Version	1.1 (85 HK) Hatchback, 5-dørs FWD M5
Karrosseritype	Hatchback	Farve	Blå	Reg. dato	30-01-2019
Drivkraft	Benzin	Drivlinje	Front wheel drive	Geartype	Manuel
KM. stand	32774.3	Antal nøgler	2	Kontraktnummer	1006680

Udvendige billeder











Date
Inspection
no.
Performed
by

Department

64896

CS

FDM Test & Bilsyn Ballerup

17-05-2025 12:15

Dæk og mønster

Position	Mærke	Størrelse	Slidbane	Dæktype
Venstre, For	Michelin	195/55-16	05 mm	Sommer
Venstre, Bag	Michelin	195/55-16	05 mm	Sommer
Højre, Bag	Michelin	195/55-16	05 mm	Sommer
Højre, For	Michelin	195/55-16	05 mm	Sommer

Ekstra hjul

Ekstrahjul tilstede

Nej

Position	Mærke	Dæktype
Ekstrahjul		

Reservedæk og rep. kit

Rep. kit tilstede Ja Reservehjul tilstede Ikke relevant

Position	Mærke	Størrelse	Slidbane	
Reservehjul		/-		





Date Inspection no. Performed

Department

by

17-05-2025 12:15 64896

CS

FDM Test & Bilsyn Ballerup

Præsentationsbilleder























Date
Inspection
no.
Performed
by

Department

64896

CS

FDM Test & Bilsyn Ballerup

17-05-2025 12:15

Mangler / Tilstand

Ref Sted Del	Туре	Handling	
--------------	------	----------	--

Skader

Ref	Sted	Del	Туре	Handling
#1	V. panel	Indstigning Venstre Bag	Rids	K4
#2	Fælge	Hjulkapsel	Ridset	K5
#3	Fælge	Hjulkapsel	Ridset	K5
#4	V. forskærm	Skærm	Bule(r)	K4
#5	Fælge	Hjulkapsel	Ridset	K5
#6	Fælge	Hjulkapsel	Ridset	K5
#7	H. fordør	Dør	Bule(r)	K3



Sted	V. panel
Del	Indstigning Venstre Bag
Туре	Rids



Sted	V. panel
Del	Indstigning Venstre Bag
Туре	Rids



Sted	Fælge
Del	Hjulkapsel
Туре	Ridset



Date
Inspection
no.
Performed

Department

by

64896

CS

FDM Test & Bilsyn Ballerup

17-05-2025 12:15







Sted	Fælge
Del	Hjulkapsel
Туре	Ridset



Sted Fælge
Del Hjulkapsel
Type Ridset



StedV. forskærmDelSkærmTypeBule(r)



Sted V. forskærm

Del Skærm

Type Bule(r)



Sted Fælge
Del Hjulkapsel
Type Ridset



Sted Fælge
Del Hjulkapsel
Type Ridset



Sted Fælge
Del Hjulkapsel
Type Ridset



Sted Fælge
Del Hjulkapsel
Type Ridset



17-05-2025 12:15 Date Inspection no. Performed

64896 CS

by FDM Test & Bilsyn Department Ballerup



Sted	Fælge
Del	Hjulkapsel
Туре	Ridset



Sted	H. fordør
Del	Dør
Туре	Bule(r)



Sted	H. fordør
Del	Dør
Туре	Bule(r)

Evt. Mekaniske fejl

Bemærkninger vedr. mekaniske fejl

Fabriksudstyr

Trend	Without roof rack	With complex reflector headlight design
Blazer Blue	Without external sill trims	With front headlight level adjustment
Comfort Package 1	Without exterior door frame mouldings	Both electrically heated exterior mirrors with BL
Rain sensor	Without door edge protection profiles	With daytime running lights
Passenger airbag deactivation	Driver's seat backrest with map pocket	With automatic headlight adjustment and wipers
Anti-lock braking system (ABS)	Front passenger seat backrest with map pocket	Rear lights - Level 1
Electrically adjustable and heated exterior mirrors	With fixed front passenger seat	With additional brake light
Exterior mirrors in body colour	Without folding/sliding driver's seat	With daytime running lights
Indicator lights integrated in exterior mirrors	Without driver seat armrests	With automatic windscreen wipers





17-05-2025 12:15 Date Inspection 64896 no. Performed CS by FDM Test & Bilsyn Department

Ballerup

With heated washer nozzles	With 2-way adjustable driver's backrest	On-board/computer consumption
With controlled rear windshield wiper/washer system	With fixed rear seat cushion	Cool & Sound Package
With rear spoiler	Without lumbar support for front passenger seat	Roof spoiler in body colour
With rear spoiler	With manual 2-way front passenger seat adjustment	Easy Driver Package
With rear spoiler	Without trailer hitch	Electronic brake-force distribution (EBD)
With rear spoiler	Without pre-equipment for towing	Electronic stability program (ESP)
With plastic rear bumper - twin	Standard engine power	Smart Regenerative Charging
With tinted windows, standard	With device dock	Hill start assist
Standard green-tinted windshield	Gear knob - MIC insert	Emergency brake assist
Only for heated windshield	Gear lever gaiter	Lane keeping assistant
Multimedia system equipment 15	Child safety lock	Electric front windows with comfort operation
With steering wheel radio controls	Without Ford Key Free system	Velour floor mats - front
With 6 radio speakers	With roof in body colour	Speed limiter
With media hub	Without body stripe - body colour	5-speed transmission - Type: 5MX65
Vehicle emergency system	Contrast colour front bumper	Interior filter: dust and pollen filter
With on-board computer	Without front license plate holder	Intelligent Protection System (IPS)
With on-board computer	Without energy-absorbing bumper reinforcement	Isofix attachments for child seat
DM4-TFT for Sync II	Without inflatable knee bolster - passenger side	Body: 5-door
Tire pressure sensors - 433 Mhz	Left head protection airbag	Mechanically adjustable rear headrests (3 pieces)
Tire pressure monitoring Version II	Right head protection airbag	Black radiator grille
With enhanced instrument cluster	Without rear side airbags	Paint in Blazer Blue
Adjustable speed limiting device	Without knee airbag - driver's side	Height-/length- adjustable steering column
With driver airbag	Seat belts active in outer rear row	Front armrest with storage compartment and 12V socket
With passenger airbag	With manually adjustable front seat belts	Central console
With driver airbag	Lashing points Style 1	Engine 1.1 Ltr 63 kW CAT
With passenger airbag	16 x 6.5	My Key (2nd programmable vehicle key)





Date 17-05-2025 12:15
Inspection no. 64896
Performed by CS

Department

FDM Test & Bilsyn Ballerup

With driver-side airbag	Without spare wheel	Fog lights with static cornering light
With passenger-side airbag	With spoke wheel covers	Petrol particulate filter (OPF)
With deactivation of passenger airbag	Without wheel caps	Tire repair kit
With luggage compartment cover	Wheel nuts without locking wheel bolts	Tire pressure monitoring system
With small roof console	With standard profile - any manufacturer	Split rear seat
With front velour floor mats	Parts only for steel wheels	Foldable rear seat backrest
With front velour floor mats	Without engine speed control	Low emissions according to Euro 6 emissions standard
With front velour floor mats	Starter/clutch pedal lock	Low emissions according to Euro 6d- TEMP emissions standard
Refrigerant - air conditioning HF01234YF	4.313	Headlights with delayed shutdown
With pollen filter	Without exhaust pipe extension	Headlight assistant with day/night sensor
With pollen filter	With plastic moulded handbrake lever	Electric power steering
With circulation heater	With unpainted brake calipers	Height-adjustable driver's seat
With additional air heater	Gear 3.92/2.19/1.41/1.03/0.811	Left sun visor with mirror
With additional air heater	Without automatic transmission with manual shifting	Right sun visor with mirror
With heated driver's seat	For unleaded fuel	Steel wheels 6x15
With heated passenger seat	For fuel with 95 octane	Start/Stop system
Standard front seats	Fuel filler cap with lock	Bumper in body colour
With manual 4-way adjustment, driver's	Standard pedal design	Daytime running lights
With manual 4-way adjustment, driver's	Without electronic speed limiter	Exterior door handles in body colour
With split/fold rear seat	Analog instruments medium version	Tinted windows
With split/fold rear seat	With speedometer (km/h)	Warning system for rear seat belts
With folding seat in 2nd row	Electric two-tone horn	Central locking with remote control
With 2-way adjustable front headrest	Without driver impairment monitoring	Windscreen wipers with rain sensor
With 2-way adjustable front headrest	Without acoustic speed warning	Winter Package
With center rear headrest	Without speed sign recognition	Intersection / Tira / View / Ebony
With center rear headrest	Without theft alarm	Without roof conversion





Date 17-05-2025 12:15
Inspection no. 64896
Performed by CS

Department

FDM Test & Bilsyn

Ballerup

Without rear mud flaps	Without automatic parking assistance	Power front windows with one-touch function
Without interior package	Without additional CD player	Power front windows with one-touch function
Without front mud	ICE - Audio, medium version with BVC	Window Pack 4
Not a special purpose vehicle	ICP medium extended	With central locking
Assembly plant: Niehl	Without radio subwoofer	With central locking
Without off-road package	Without mobile phone interface	Remote door opening - 2 folding keys
Without equipment marketing preparation	Without smoker package	Remote door opening - 2 folding keys
Exclusive Pack	Without cigarette lighter	With central locking
Without sales emblem	Without special equipment packages	Driver/passenger/rear/ EU T&S seatbelt warning
Without special paint	Without fog light installation	Restraint system package 2
Without SVO application/stickers	Without cornering lights	Driver/passenger seatbelt pretensioners
Marketing level 1	Without interior lights	With electrochromic rearview mirror
Manual air conditioning	With entry light - headliner	With electrochromic rearview mirror
Without SIP	Without entry lights	With additional power socket
Solid paint	Without heated steering wheel	With Isofix attachment
Fiesta Carline Badge	Without rear parking aid	With IVD/traction control/ABS
Without cooling equipment	Without special equipment kit	Disc brakes front/drum brakes rear
For moderate climates	Without navigation system	Electronic emergency brake assist
Without SVO except packages	Without camera	Lane change warning system
Without tailgate emblem	Without blind spot information system	Lane keeping assist
Less Marketing Driver Assist Pack	With (hard) polyurethane steering wheel	195/55R16 tires
Driver/passenger sun visor with mirror and light	Without front door sill protection	Tire repair kit SVC
Without all- round/automatic locking function	With standard suspension	Without spare wheel
Manual rear side windows	Without collision avoidance system	With manual adjustable steering column
Without console ashtray	Standard front seats	With manual adjustable steering column
Storage compartment - basic equipment	Without driver seat lumbar support	With IVD/traction control/ABS





Date 17-05-2025 12:15
Inspection no. 64896
Performed by CS
Department FDM Test & Bilsyn Ballerup

Without rear foot mats	Without fog lights	With IVD/traction control/ABS
With full headliner - shaped part	Without front parking aid	With IVD/traction control/ABS
With door trim panel, level 2	With visibility package	LHD FWD
Less rear seat ash tray	USB 2 accessory incl. iPod function	With hill start assist
Without load shelf	5-door sedan	5-speed manual transmission Getrag - 5MX65
Hold-back - first aid kit	Blazer Blue	Euro 6.2 emissions standard
With warning triangle holders	Top grille with chrome finish	Start/stop system
Rear door trim panel - plastic	Both electrically heated exterior mirrors with BL	1.1L Duratec TI-VCT PFI 85PS
Without active radiator grille	Body-colored exterior mirror	(-) SVP

